



VEHICLE INSPECTION REPORT

RO67HSE

Fiat 500 0.9 TwinAir Lounge 3dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	30/09/2017	Keys	2	CAP Clean	£3,450.00
Year	2017	Service history	Yes	CAP Average	£2,925.00
Mileage	89,298 Miles Warranted	Service documents	Service Book	CAP Below	£2,400.00
Fuel Type	PETROL	Number of stamps	8	Gearbox	MANUAL
Colour	PINK	Last service date	25/09/2025	Gears	5
VIN	ZFA3120000J868969	Last service miles	80,336	Doors	3
Body Style	Hatchback	MOT Due	29/09/2026		

Last service 25/09/2025 at 80,336 miles- 8 services (2 main dealer) Exhaust blowing engine tapping

Tyres

NSF	CONTINENTAL	6.0mm
NSR	CONTINENTAL	6.0mm
OSF	CONTINENTAL	6.0mm
OSR	CONTINENTAL	6.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Central locking
- Cruise control
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Remote central locking
- PAS
- Digital radio
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Passenger airbag
- Partial leather seat trim
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Chipped
1 To 5



5: Door Window nsf
Scratched
Over 30mm



6: Door nsf
Chipped
Edge Chip



7: Qtr Panel nsr
Chipped
1 To 5



8: Wheel nsr
Scratched
Over 50mm




9: Bumper Rear
Scratched
25 to 100mm Thru Paint



10: Bumper Rear
Dented
Between 10mm + 30mm



11: Roof
Dented
Hail - Moderate



12: Qtr Panel osr
Dented
Over 30mm



13: Wheel osr
Scratched
Over 50mm



14: Wheel osf
Scratched
Over 50mm



15: Wing osf
Scratched
UpTo 25mm Thru Paint

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK