



# VEHICLE INSPECTION REPORT

**GU17WEA**

## Vauxhall Viva 1.0 SE 5dr [A/C]

| Inspection      |    | Vehicle |         |
|-----------------|----|---------|---------|
| Serious Damage? | No | VAT     | Margin  |
|                 |    | V5      | Present |

nama  
GRADE  
**3**

### Details

|           |                        |                   |              |                    |            |
|-----------|------------------------|-------------------|--------------|--------------------|------------|
| Reg. date | 30/03/2017             | Body Style        | Hatchback    | Last service miles | 50,459     |
| Year      | 2017                   | Keys              | 2            | MOT Due            | 30/03/2027 |
| Mileage   | 52,997 Miles Warranted | Service history   | Yes          | Gearbox            | MANUAL     |
| Fuel Type | PETROL                 | Service documents | Service Book | Gears              | 5          |
| Colour    | BLUE                   | Number of stamps  | 4            | Doors              | 5          |
| VIN       | W0LDD6E79HC790325      | Last service date | 11/03/2026   |                    |            |

LAST SERVICE 11/03/2026 @ 50,459 MILES (4 SERVICES, 2 MAIN DEALER) Eml light on car has been plugged in and detects

A camshaft position timing -over -advanced or system performance ( Bank1)

Nsf window gaulty

### Tyres



|       |        |       |
|-------|--------|-------|
| NSF   | BUDGET | 5.0mm |
| NSR   | BUDGET | 5.0mm |
| OSF   | BUDGET | 5.0mm |
| OSR   | BUDGET | 5.0mm |
| Spare |        |       |

## Features


- Bluetooth connection
- Service indicator
- Electric door mirrors
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags
- Steel wheels
- Cruise control
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- PAS
- Media storage
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Rear wiper
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim

## Photos







## Condition Check




## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Scratched  
25 to 100mm Thru Paint



3: Door nsf  
Dented  
Over 30mm



4: Door nsf  
Chipped  
Edge Chip



5: Door nsr  
Dented  
Over 30mm



6: Bumper Rear  
Chipped  
1 To 5



7: Qtr Panel osr  
Scratched  
UpTo 25mm Thru Paint




8: Door osr  
Dented  
With Paint Damage



9: Door osf  
Chipped  
Edge Chip



10: Wing osf  
Scratched  
UpTo 25mm Thru Paint



11: Roof  
Chipped  
1 To 5

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

|               |    |                                                |    |
|---------------|----|------------------------------------------------|----|
| Engine Runs   | OK | Gearbox 1st and Reverse Test                   | OK |
| Brakes        | OK | Clutch Slip Test from Static                   | OK |
| Parking Brake | OK | Gearbox Static Gear Selection (engine running) | OK |
|               |    | No Excessive Smoking                           | OK |

|                          |       |                                     |    |
|--------------------------|-------|-------------------------------------|----|
| EML light illuminated    | Fault | Oil warning light illuminated       | OK |
| Airbag light illuminated | OK    | Service indicator light illuminated | OK |
| ABS light illuminated    | OK    |                                     |    |
| Windows                  | OK    | Radio                               | OK |
|                          |       | Steering                            | OK |