



VEHICLE INSPECTION REPORT

ML13XJE

Audi A3 1.6 TDI SE 5dr

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 Present

nama
GRADE
4

Details

Reg. date	29/05/2013	Keys	2	CAP Average	£2,125.00
Year	2013	Service history	Yes	CAP Below	£1,675.00
Mileage	108,315 Miles Warranted	Service documents	Printout	Gearbox	MANUAL
Fuel Type	DIESEL	Number of stamps	8	Gears	6
Colour	GREY	Last service date	07/01/2025	Doors	5
VIN	WAUZZZ8V9DA065220	MOT Due	24/11/2026		
Body Style	Hatchback	CAP Clean	£2,575.00		

£90 ADDITIONAL FEE

LAST SERVICE 07/01/2025 @ UNKNOWN MILEAGE (8 SERVICES, 3 MAIN DEALER)

Vibration when pulling away

Tyres

NSF	HANKOOK	2.0mm
NSR	HANKOOK	4.0mm
OSF	HANKOOK	3.0mm
OSR	HANKOOK	5.0mm
Spare		

Features


- Bluetooth connection
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Remote central locking
- Navigation system
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Central locking

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Chipped
1 To 5



3: Door osr
Dented
Over 30mm



4: Bumper Rear
Hole
UpTo 25mm



5: Qtr Panel nsr
Dented
Between 10mm + 30mm



6: Wheel nsr
Corroded
Light



7: Door nsr
Chipped
1 To 5



8: Door nsf
Chipped
Edge Chip



9: Wing nsf
Poor Previous Repair
Poor Paint



10: Bumper Front
Scratched
Over 100mm Thru Paint



11: Bonnet
Chipped
1 To 5

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
 Additional fees may apply to some vendors.
 Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK