



# VEHICLE INSPECTION REPORT

**DL68OLK**

## Audi A4 35 TFSI SE 4dr

### Inspection

Serious Damage? No

### Vehicle

VAT Margin

V5 Present

nama  
GRADE  
4

### Details

|           |                           |                   |            |                    |         |
|-----------|---------------------------|-------------------|------------|--------------------|---------|
| Reg. date | 29/01/2019                | Body Style        | Saloon     | Last service miles | 78,625  |
| Year      | 2019                      | Keys              | 2          | MOT Due            | Expired |
| Mileage   | 94,663 Miles<br>Warranted | Service history   | Yes        | Gearbox            | MANUAL  |
| Fuel Type | PETROL                    | Service documents | Printout   | Gears              | 6       |
| Colour    | BLACK                     | Number of stamps  | 3          | Doors              | 4       |
| VIN       | WAUZZZF47KN005145         | Last service date | 08/08/2024 |                    |         |

£90 ADDITIONAL FEE

MOT EXPIRED

last service 8/8/24 @ 78,625 miles (3 main dealer)

mileage incorrectly recorded for 29/7/22 on printout Brake pads worn message displayed

### Tyres

|       |         |       |
|-------|---------|-------|
| NSF   | LAUFENN | 5.0mm |
| NSR   | LAUFENN | 5.0mm |
| OSF   | LAUFENN | 5.0mm |
| OSR   | LAUFENN | 5.0mm |
| Spare |         |       |

## Features


- Bluetooth connection
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Cruise control
- PAS
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Heated front seat
- Service indicator
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

## Photos






## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front  
Scratched  
25 to 100mm Thru Paint



3: Bumper Front  
Chipped  
Multiple Chips



4: Wing nsf  
Chipped  
Multiple Chips



5: A Post ns  
Scratched  
UpTo 25mm Thru Paint



6: Door nsf  
Scratched  
Over 25mm Thru Paint



7: Door nsr  
Chipped  
Edge Chip



8: Qtr Panel nsr  
Scratched  
UpTo 25mm Thru Paint



9: Bumper Rear  
Scratched  
Up To 25mm Thru Paint



10: Other  
N/A  
N/A



11: Boot Lid  
Scratched  
Up To 25mm Thru Paint



12: Qtr Panel osr  
Poor Previous Repair  
Rippled Up To 30%



13: Door osr  
Dented  
Between 10mm + 30mm



14: Door osr  
Scratched  
Up To 25mm Thru Paint



15: Door osf  
Scratched  
UpTo 25mm Thru Paint



16: Wing osf  
Scratched  
Over 25mm Thru Paint



17: A Post os  
Chipped  
1 To 5



18: Roof  
Chipped  
Edge Chip

### Interior

**Carpet Condition**                      Average  
**Seat Condition**                      Average

**Upholstery Condition**              Average  
**Odour**                                      No

### Vehicle Inspection Report

**Disclaimer**  
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.  
Additional fees may apply to some vendors.  
Please note buyers rate increase from 01/01/2025

|                |    |                                                |    |
|----------------|----|------------------------------------------------|----|
| Engine Runs    | OK | Gearbox 1st and Reverse Test                   | OK |
| Brakes         | OK | Clutch Slip Test from Static                   | OK |
| Turbo Boosting | OK | Gearbox Static Gear Selection (engine running) | OK |
|                |    | No Excessive Smoking                           | OK |

|                          |    |                                     |    |
|--------------------------|----|-------------------------------------|----|
| EML light illuminated    | OK | Oil warning light illuminated       | OK |
| Airbag light illuminated | OK | DPF light illuminated               | OK |
| ABS light illuminated    | OK | Service indicator light illuminated | OK |
| Windows                  | OK | Radio                               | OK |
| Sat nav                  | OK | Steering                            | OK |