



VEHICLE INSPECTION REPORT

DE12LVK

Audi A1 1.6 TDI Sport 3dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	30/03/2012	Body Style	Hatchback	Last service miles	100,014
Year	2012	Keys	1	MOT Due	29/10/2026
Mileage	105,128 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	DIESEL	Service documents	Service Book	Gears	5
Colour	SILVER	Number of stamps	7	Doors	3
VIN	WAUZZZ8X5BB073162	Last service date	29/10/2025		

last service 29/10/25 @ 100,014 miles (7 services) book & print
replaced timing belt & water pump on 30/10/20 @ 61,432 miles

Tyres

NSF	BUDGET	6.0mm
NSR	WESTLAKE	5.0mm
OSF	BUDGET	6.0mm
OSR	WESTLAKE	5.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Cloth seat trim
- Navigation system
- Digital radio
- Front fog lights
- Front head restraints
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- PAS
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Drivers airbag
- Central locking
- Rear wiper
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos



1: Wheel of
Scratched
Over 50mm



2: Wing of
Chipped
1 To 5



3: A Post os
Chipped
1 To 5



4: Door osf
Chipped
1 To 5



5: Door osf
Chipped
Edge Chip



6: Qtr Panel osr
Chipped
1 To 5



7: Wheel osr
Scratched
Up To 50mm



8: Bumper Rear
Poor Previous Repair
Paint Flake



9: Wheel nsr
Scratched
Over 50mm



10: Qtr Panel nsr
Poor Previous Repair
Poor Paint



11: Door nsf
Poor Previous Repair
Poor Paint



12: Wheel nsf
Scratched
Over 50mm



13: Bumper Front
Scratched
UpTo 25mm Thru Paint



14: Bumper Front
Chipped
Multiple Chips



15: Bonnet
Chipped
1 To 5



16: Roof
Chipped
1 To 5



17: Seat Back Cover osf
Scuffed
Over 25mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK