



VEHICLE INSPECTION REPORT

LM19VUA

Toyota Hilux Icon D/Cab Pick Up 2.4 D-4D

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present



Details

Reg. date	31/05/2019	Body Style	Light 4X4 Utility	Last service miles	44,000
Year	2019	Keys	2	MOT Due	29/04/2027
Mileage	45,189 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	DIESEL	Service documents	Printout	Gears	6
Colour	GREY	Number of stamps	5		
VIN	AHTHB3CD202132911	Last service date	18/03/2026		

Last Service - 18.03.2026 at 44000 miles (5 services)


Tyres


NSF	BRIDGESTONE	7.0mm
NSR	BRIDGESTONE	7.0mm
OSF	BRIDGESTONE	7.0mm
OSR	BRIDGESTONE	7.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Rear electric windows
- Central locking
- Cruise control
- Digital radio
- Metallic Paint
- Cloth seat trim
- Front parking sensor
- Air conditioning
- Drivers airbag
- Park assist camera
- Front electric windows
- Passenger airbag

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wing nsf
Chipped
1 To 5



4: Door nsf
Dented
Over 30mm



5: Door nsf
Scratched
Over 25mm Thru Paint



6: Door nsr
Dented
Over 30mm



7: Wheel nsr
Scratched
Over 50mm



8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



9: Tailgate
Dented
With Paint Damage



10: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



11: C Post os
Scratched
Over 25mm Thru Paint



12: Door osr
Scratched
Over 25mm Thru Paint



13: Door osf
Dented
Between 10mm + 30mm



14: Wing osf
Scratched
Over 25mm Thru Paint



15: Wheel of
Scratched
Over 50mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK