



VEHICLE INSPECTION REPORT

YT14URX

Ford Fiesta 1.0 EcoBoost Zetec 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	06/03/2014	Body Style	Hatchback	MOT Due	31/10/2026
Year	2014	Keys	1	Gearbox	MANUAL
Mileage	89,585 Miles Warranted	Service history	Yes	Gears	5
Fuel Type	PETROL	Service documents	Service Book	Doors	5
Colour	RED	Number of stamps	8		
VIN	WF0DXXGAKDEL06070	Last service date	03/02/2026		

£100 ADDITIONAL FEE

LAST SERVICE 03/02/2026 @ 8300 MILES

CAMBELT AND WATERPUMP REPLACED 31.07.2023 @ 64012 MILES

Tyres

NSF	BUDGET	6.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	6.0mm
Spare		

Features


- Bluetooth connection
- Radio/CD
- Front electric windows
- Drivers airbag
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Rear wiper
- Electric door mirrors
- Solid Paint
- Traction control
- Alloy wheels
- Telephone
- Air conditioning
- ABS
- Central locking

Photos





Condition Check



Damage Photos



1: Wing osf
Chipped
1 To 5



2: Door osf
Chipped
1 To 5



3: Qtr Panel osr
Chipped
1 To 5




4: Tailgate
Poor Previous Repair
Paint Flake



5: Bumper Rear
Scratched
25 to 100mm Thru Paint



6: Qtr Panel nsr
Dented
With Paint Damage



7: Door nsr
Dented
With Paint Damage



8: Door nsf
Chipped
1 To 5



9: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



10: Wing nsf
Poor Previous Repair
Poor Paint



11: Wheel nsf
Scratched
Over 50mm



12: Bumper Front
Poor Previous Repair
Poor Paint



13: Bonnet
Chipped
1 To 5

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK