



VEHICLE INSPECTION REPORT

EA16MHF

Nissan Qashqai 1.5 dCi N-Connecta 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Photocopy



Details

Reg. date	31/03/2016	Body Style	Hatchback	Last service miles	63,968
Year	2016	Keys	2	MOT Due	12/01/2027
Mileage	80,720 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	DIESEL	Service documents	Service Book	Gears	6
Colour	WHITE	Number of stamps	7	Doors	5
VIN	SJNFAAJ11U1609014	Last service date	13/01/2023		

COPY OF V5

Last service 13/01/2023 at 63,968 miles- 7 services

Tyres


NSF	CONTINENTAL	5.0mm
NSR	MICHELIN	5.0mm
OSF	FALKEN	6.0mm
OSR	GOODYEAR	5.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Fixed panoramic glass roof
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- PAS
- Digital radio
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Navigation system
- Rear wiper
- Electric door mirrors
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Chipped
1 To 5



3: Wheel nsf
Corroded
Light



4: Door nsr
Dented
With Paint Damage



5: Wheel nsr
Corroded
Light



6: Bumper Rear
Scratched
25 to 100mm Thru Paint



7: Wheel osr
Scratched
Over 50mm



8: Qtr Panel osr
Chipped
1 To 5



9: Door osr
Dented
Between 10mm + 30mm



10: Door osf
Dented
Over 30mm



11: Wing osf
Chipped
1 To 5



12: Wheel osf
Corroded
Light



13: Screen Front
Chipped
Over 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK