



VEHICLE INSPECTION REPORT

FT19XEC

Mitsubishi Outlander 2.4 PHEV 4h 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	31/05/2019	Body Style	Estate	Last service miles	99,462
Year	2019	Keys	2	MOT Due	05/06/2027
Mileage	104,692 Miles Warranted	Service history	Yes	Gearbox	CVT
Fuel Type	HYBRID ELECTRIC	Service documents	Service Book	Gears	1
Colour	WHITE	Number of stamps	7	Doors	5
VIN	JMAXDGG3WKZ008959	Last service date	10/03/2026		

£90 ADDITIONAL FEE

last service 10/3/26 @ 99,462 miles (7 services 4 main dealer) book & print 3 pin charging cable

Tyres


NSF	SAILUN	5.0mm
NSR	GT RADIAL	5.0mm
OSF	SAILUN	6.0mm
OSR	SAILUN	5.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Electrically adjustable drivers seat
- Rear headrests
- Passenger airbag
- Remote central locking
- Cruise control
- Rear wiper
- Electric door mirrors
- Front armrest
- Solid Paint
- Traction control
- Leather seat trim
- Heated front seat
- Telephone
- Air conditioning
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Park assist camera
- Radio/CD
- Climate control
- Rear electric windows
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Wing osf
Chipped
Over 5mm



2: Door osr
Chipped
1 To 5



3: Door osr
Chipped
Edge Chip



4: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



5: Bumper Rear
Chipped
1 To 5



6: Bumper Rear Moulding
Broken
Replace



7: Qtr Panel nsr
Rusted
Over 5mm



8: Door nsr
Chipped
1 To 5



9: Door nsr
Chipped
Edge Chip



10: Wing nsf
Chipped
1 To 5




11: Bonnet
Chipped
1 To 5



12: Bumper Front
Chipped
1 To 5



13: A Post os
Chipped
1 To 5



14: Roof
Chipped
1 To 5

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK