



VEHICLE INSPECTION REPORT

DV10HHD

Hyundai IX35 2.0 CRDi Style 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Buyer To Apply



Details

Reg. date	02/08/2010	Service history	Yes	CAP Average	£480.00
Year	2010	Service documents	Printout	CAP Below	£150.00
Mileage	147,980 Miles Warranted	Number of stamps	9	Gearbox	MANUAL
Fuel Type	DIESEL	Last service date	11/08/2022	Gears	6
Colour	GREY	Last service miles	123,319	Doors	5
VIN	U5YZT81VNBL037380	MOT Due	03/09/2026		
Body Style	Estate	CAP Clean	£880.00		

NO V5


Last service 11/08/2022 at 123,319 miles- 9 services Noisy engine

Tyres


NSF	HANKOOK	5.0mm
NSR	HANKOOK	5.0mm
OSF	HANKOOK	5.0mm
OSR	HANKOOK	5.0mm
Spare		

Photos





Condition Check



Damage Photos



1: Wing osf
Scratched
Over 25mm Thru Paint



2: Door osf
Scratched
Over 25mm Thru Paint



3: Door osr
Scratched
Over 25mm Thru Paint



4: Qtr Panel osr
Chipped
1 To 5



5: Bumper Rear
Poor Previous Repair
Paint Flake



6: Qtr Panel nsr
Dented
With Paint Damage



7: Door nsr
Dented
With Paint Damage



8: Door nsf
Chipped
Edge Chip



9: Door nsf
Chipped
1 To 5



10: Wheel nsf
Scratched
Up To 50mm



11: Bumper Front
Scratched
25 to 100mm Thru Paint



12: Bumper Front
Chipped
Multiple Chips



13: Bonnet
Scratched
Over 25mm Thru Paint



14: Seat Base Cover osf
Torn
UpTo 3mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK