



VEHICLE INSPECTION REPORT

AK15HSJ

Ford Fiesta 1.25 82 Zetec 3dr

Cat: N Incident History

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 Present

nama
GRADE
5

Details

Reg. date	31/03/2015	Body Style	Hatchback	Last service miles	39,630
Year	2015	Keys	1	MOT Due	12/05/2027
Mileage	104,188 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Printout	Gears	5
Colour	WHITE	Number of stamps	1	Doors	3
VIN	WF0CXXGAKCFK23468	Last service date	19/08/2020		

Category N Insurance Loss. No Structural Damage and Repairable - Insurer Decided Not to Repair

CAT S ON 15/03/2022

CAT N ON 22/07/2023

LAST SERVICE 19/08/2020 @ 39,630 MILES (1 SERVICE)

Tyres

NSF	BUDGET	5.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Body coloured bumpers
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear wiper
- Electric door mirrors
- Solid Paint
- Traction control
- Cloth seat trim
- Telephone
- Air conditioning
- ABS
- Tyre pressure monitor
- Alloy wheels
- Radio/CD
- Front electric windows
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Chipped
1 To 5



3: Sill os
Rusted
Over 5mm



4: Qtr Panel osr
Dented
Over 30% Of Panel



5: Bumper Rear
Poor Previous Repair
Paint Flake



6: Qtr Panel nsr
Dented
With Paint Damage



7: Door nsf
Chipped
Edge Chip



8: Wheel nsf
Scratched
Over 50mm



9: Bumper Front
Scratched
Over 100mm Thru Paint



10: Bonnet
Chipped
1 To 5



11: Roof
Chipped
1 To 5



12: Door osf
Scratched
UpTo 25mm Thru Paint



13: Door osf
Chipped
Edge Chip

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK