



VEHICLE INSPECTION REPORT

KE14ASU

Audi Q5 SQ5 Quattro 5dr Tip Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Buyer To Apply



Details

Reg. date	01/08/2014	Body Style	Estate	Last service miles	60,421
Year	2014	Keys	2	MOT Due	10/04/2027
Mileage	79,408 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	DIESEL	Service documents	Printout	Gears	8
Colour	BLACK	Number of stamps	6	Doors	5
VIN	WAUZZZ8R6FA021407	Last service date	27/10/2023		

NO V5
LAST SERVICE 27/10/2023 @ 60,421 MILES (6 SERVICES)

Tyres


NSF	MICHELIN	3.0mm
NSR	MICHELIN	3.0mm
OSF	MICHELIN	3.0mm
OSR	MICHELIN	3.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Telephone
- Electric sunroof
- Electrically adjustable passenger seat
- Rear headrests
- Passenger airbag
- Remote central locking
- Cruise control
- Park assist camera
- Radio/CD
- Air conditioning
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Heated front seat
- Rear wiper
- Electric door mirrors
- Electrically adjustable drivers seat
- Rear electric windows
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Door osf
Chipped
Edge Chip



2: Door osr
Scratched
UpTo 25mm Thru Paint



3: Door osf
Scratched
UpTo 25mm Thru Paint



4: Door osr
Chipped
Edge Chip




5: Qtr Panel osr
Chipped
1 To 5



6: Qtr Panel nsr
Chipped
1 To 5



7: Wheel nsr
Scratched
Up To 50mm



8: Door nsr
Chipped
1 To 5



9: Wing nsf
Chipped
1 To 5



10: Bonnet
Chipped
1 To 5



11: Wheel osr
Scratched
Up To 50mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		