



VEHICLE INSPECTION REPORT

LD69FCJ

Kia Sportage 1.6T GDi ISG GT-Line 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	23/11/2019	Keys	2	CAP Clean	£10,650.00
Year	2019	Service history	Yes	CAP Average	£9,525.00
Mileage	36,588 Miles Warranted	Service documents	Service Book	CAP Below	£8,400.00
Fuel Type	PETROL	Number of stamps	2	Gearbox	MANUAL
Colour	WHITE	Last service date	29/10/2021	Gears	6
VIN	U5YPK816LLL832266	Last service miles	13,351	Doors	5
Body Style	Estate	MOT Due	03/12/2026		

£100 ADDITIONAL FEE

last service 29/10/21 @ 13,351 miles (2 main dealer)

Tyres

NSF	MATADOR	4.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim
- Heated front seat
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Navigation system
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking

Photos





Condition Check




Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wheel osr
Scratched
Over 50mm



3: Bumper Rear
Chipped
Multiple Chips



4: Wheel nsr
Corroded
Light



5: Door nsr
Chipped
Edge Chip



6: Door nsr
Dented
Between 10mm + 30mm



7: Door nsf
Chipped
Edge Chip



8: Door nsf
Chipped
1 To 5



9: Wheel nsf
Scratched
Up To 50mm



10: Bumper Front
Chipped
1 To 5



11: Bonnet
Chipped
1 To 5



12: Bumper Front Moulding
Scratched (Painted)
Over 25mm Thru Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK