



VEHICLE INSPECTION REPORT

GN69YXY

Audi A1 30 TFSI S Line 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	05/09/2019	Body Style	Hatchback	Last service miles	67,702
Year	2019	Keys	2	MOT Due	16/06/2027
Mileage	75,836 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Printout	Gears	6
Colour	BLACK	Number of stamps	5	Doors	5
VIN	WAUZZZGB4KR061369	Last service date	07/03/2026		

£90 ADDITIONAL FEE

last service 7/3/26 @ 67,702 miles (5 services 4 main dealer)

Tyres


NSF	RAPID	6.0mm
NSR	RAPID	6.0mm
OSF	RAPID	6.0mm
OSR	FALKEN	3.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Cruise control
- Steering wheel mounted controls
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- PAS
- Digital radio
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Bumper Front
Dented
With Paint Damage



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



6: Door nsf
Scratched
Over 25mm Thru Paint



7: Door nsr
Scratched
Over 25mm Thru Paint



8: Wheel nsr
Scratched
Over 50mm



9: Door nsf
Dented
Between 10mm + 30mm



10: Door nsr
Dented
Between 10mm + 30mm



11: Qtr Panel nsr
Dented
Between 10mm + 30mm



12: Bumper Rear
Scratched
Over 100mm Thru Paint



13: Qtr Panel osr
Dented
Over 30mm



14: Door nsr
Scratched
UpTo 25mm Thru Paint



15: Door osf
Scratched
Over 25mm Thru Paint



16: Roof
Chipped
Edge Chip

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK