



VEHICLE INSPECTION REPORT

GY61EWT

Fiat 500 1.2 Lounge 3dr [Start Stop]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	30/09/2011	Body Style	Hatchback	Last service miles	93,324
Year	2011	Keys	1	MOT Due	05/10/2026
Mileage	119,592 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Service Book	Gears	5
Colour	WHITE	Number of stamps	9	Doors	3
VIN	ZFA31200000748868	Last service date	06/10/2021		

Last Service - 06.10.2021 at 93324 miles (9 services)
Exhaust blowing / rattling

Tyres

NSF	HIFLY	5.0mm
NSR	BUDGET	4.0mm
OSF	HIFLY	5.0mm
OSR	BUDGET	4.0mm
Spare		

Features


- Rear wiper
- Electric door mirrors
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Telephone
- Fixed panoramic glass roof
- Solid Paint
- Traction control
- Leather seat trim
- Radio/CD
- Air conditioning
- ABS
- Central locking
- Alloy wheels
- Body coloured bumpers
- Front electric windows
- Drivers airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Chipped
1 To 5



3: Door osf
Scratched
Up To 25mm Thru Paint



4: Door osf
Chipped
Edge Chip




5: Qtr Panel osr
Dented
Between 10mm + 30mm



6: Wheel osr
Scratched
Up To 50mm



7: Bumper Rear
Scratched
Up To 25mm Thru Paint



8: Qtr Panel nsr
Chipped
1 To 5



9: Roof
Poor Previous Repair
Paint Flake



10: Door nsf
Dented
Over 30mm



11: Wheel nsf
Scratched
Over 50mm




12: Wing nsf
Chipped
1 To 5



13: Bonnet
Chipped
Multiple Chips



14: Bumper Front
Chipped
Multiple Chips



15: A Post os
Chipped
1 To 5

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK