



## VEHICLE INSPECTION REPORT

**GC14KMA**

### Nissan Qashqai 1.5 dCi Acenta [Smart Vision Pack] 5dr

#### Inspection

Serious Damage? No

#### Vehicle

VAT Margin

V5 Present

nama  
GRADE  
3

#### Details

|           |                           |                   |              |                    |            |
|-----------|---------------------------|-------------------|--------------|--------------------|------------|
| Reg. date | 31/07/2014                | Body Style        | Hatchback    | Last service miles | 39,804     |
| Year      | 2014                      | Keys              | 2            | MOT Due            | 15/06/2027 |
| Mileage   | 91,171 Miles<br>Warranted | Service history   | Yes          | Gearbox            | MANUAL     |
| Fuel Type | DIESEL                    | Service documents | Service Book | Gears              | 6          |
| Colour    | BLACK                     | Number of stamps  | 3            | Doors              | 5          |
| VIN       | SJNFAAJ11U1167878         | Last service date | 16/04/2019   |                    |            |

Last Service - 16.04.2019 at 39804 miles (3 services)

#### Tyres

|       |         |       |
|-------|---------|-------|
| NSF   | JOYROAD | 5.0mm |
| NSR   | PACE    | 6.0mm |
| OSF   | PACE    | 6.0mm |
| OSR   | BUDGET  | 6.0mm |
| Spare |         |       |

## Features

- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Front parking sensor
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim


## Photos







## Condition Check



## Damage Photos



1: Wheel osf  
Scratched  
Over 50mm



2: Wing osf  
Chipped  
1 To 5



3: Door osf  
Chipped  
Multiple Chips



4: Door osr  
Scratched  
Over 25mm Thru Paint



5: Qtr Panel osr  
Scratched  
UpTo 25mm Thru Paint



6: Qtr Panel nsr  
Dented  
Between 10mm + 30mm



7: Door nsr  
Chipped  
1 To 5



8: Door nsf  
Chipped  
Multiple Chips





9: Door Mirror Assy nsf  
Broken  
Replace



10: Wheel nsf  
Scratched  
Over 50mm



11: Bonnet  
Chipped  
1 To 5



12: Bumper Front  
Scratched  
25 to 100mm Thru Paint



13: Screen Front  
Chipped  
UpTo 10mm

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

|                          |    |                                                |    |
|--------------------------|----|------------------------------------------------|----|
| Engine Runs              | OK | Gearbox 1st and Reverse Test                   | OK |
| Brakes                   | OK | Clutch Slip Test from Static                   | OK |
| Turbo Boosting           | OK | Gearbox Static Gear Selection (engine running) | OK |
| Parking Brake            | OK | No Excessive Smoking                           | OK |
| EML light illuminated    | OK | Oil warning light illuminated                  | OK |
| Airbag light illuminated | OK | DPF light illuminated                          | OK |
| ABS light illuminated    | OK | Service indicator light illuminated            | OK |
| Windows                  | OK | Radio                                          | OK |
|                          |    | Steering                                       | OK |