



## VEHICLE INSPECTION REPORT

**GR08BWB**

### Vauxhall Agila 1.2i 16V Design [80] 5dr

#### Inspection

Serious Damage? No

#### Vehicle

VAT Margin

V5 Present

nama  
GRADE  
**5**

#### Details

|           |                           |                   |              |                    |        |
|-----------|---------------------------|-------------------|--------------|--------------------|--------|
| Reg. date | 31/07/2008                | Body Style        | Estate       | Last service miles | 9,355  |
| Year      | 2008                      | Keys              | 1            | Gearbox            | MANUAL |
| Mileage   | 60,156 Miles<br>Warranted | Service history   | Yes          | Gears              | 5      |
| Fuel Type | PETROL                    | Service documents | Service Book | Doors              | 5      |
| Colour    | SILVER                    | Number of stamps  | 3            |                    |        |
| VIN       | W0LFXB32S8M157228         | Last service date | 22/08/2013   |                    |        |

£50 ADDITIONAL FEE

Last service 22/08/2013 at 9355 miles- 3 services

MOT EXPIRED Exhaust blowing

High clutch

#### Tyres

|       |        |         |
|-------|--------|---------|
| NSF   | BUDGET | 5.0mm   |
| NSR   | BUDGET | Damaged |
| OSF   | BUDGET | 5.0mm   |
| OSR   | BUDGET | 5.0mm   |
| Spare |        |         |

## Features

- Rear wiper
- Air conditioning
- ABS
- Remote central locking
- Radio/CD
- Front electric windows
- Drivers airbag
- Cloth seat trim
- Body coloured bumpers
- Rear headrests
- Passenger airbag
- Alloy wheels
- Electric door mirrors
- Metallic Paint
- Central locking


## Photos







## Condition Check



## Damage Photos



1: Wheel osf  
Scratched  
Over 50mm



2: Wheel osr  
Scratched  
Over 50mm






3: Door osr  
Chipped  
1 To 5



4: Tailgate  
Dented  
2 Or Less UpTo 10mm




5: Bumper Rear  
Scratched  
Over 100mm Thru Paint



6: Qtr Panel nsr  
Dented  
Over 30% Of Panel



7: Wheel nsr  
Scratched  
Over 50mm



8: Other  
N/A  
N/A





9: Wing nsf  
Poor Previous Repair  
Poor Paint



10: Wheel nsf  
Scratched  
Over 50mm



11: Bumper Front  
Scratched  
25 to 100mm Thru Paint



12: Bonnet  
Chipped  
1 To 5



13: Roof  
Chipped  
1 To 5



14: Bumper Front  
Chipped  
Multiple Chips



15: Tyre nsr  
Damaged  
Replace

Interior

|                  |         |                      |         |
|------------------|---------|----------------------|---------|
| Carpet Condition | Average | Upholstery Condition | Average |
| Seat Condition   | Average | Odour                | No      |

Vehicle Inspection Report

**Disclaimer**  
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.  
Additional fees may apply to some vendors.  
Please note buyers rate increase from 01/01/2025

|                          |    |                                                |    |
|--------------------------|----|------------------------------------------------|----|
| Engine Runs              | OK | Gearbox 1st and Reverse Test                   | OK |
| Brakes                   | OK | Clutch Slip Test from Static                   | OK |
| Parking Brake            | OK | Gearbox Static Gear Selection (engine running) | OK |
|                          |    | No Excessive Smoking                           | OK |
| EML light illuminated    | OK | Oil warning light illuminated                  | OK |
| Airbag light illuminated | OK | Service indicator light illuminated            | OK |
| ABS light illuminated    | OK |                                                |    |
| Windows                  | OK | Radio                                          | OK |
|                          |    | Steering                                       | OK |