



VEHICLE INSPECTION REPORT

AO23JVV

Vauxhall Grandland 1.5 Turbo D GS 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	08/03/2023	Body Style	Hatchback	Last service miles	37,083
Year	2023	Keys	2	MOT Due	07/03/2027
Mileage	38,430 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	DIESEL	Service documents	Service Book	Gears	8
Colour	WHITE	Number of stamps	2	Doors	5
VIN	W0VZCYHZ0P6002716	Last service date	05/03/2026		

Last service 05/03/2026 at 37,083 miles- 2 main dealer services Carpet missing in boot

Tyres

NSF	MICHELIN	5.0mm
NSR	MICHELIN	5.0mm
OSF	MICHELIN	5.0mm
OSR	MICHELIN	5.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Solid Paint
- Traction control
- Cloth seat trim
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim
- Navigation system
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Up To 50mm




2: Door osf
Chipped
Edge Chip



3: Door osr
Chipped
Edge Chip




4: Bumper Rear Moulding
Scratched (Painted)
Over 25mm Thru Paint




5: Door nsr
Chipped
Edge Chip



6: Wheel nsf
Scratched
Up To 50mm



7: Bumper Front
Chipped
Multiple Chips



8: Bonnet
Chipped
1 To 5



9: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK