



VEHICLE INSPECTION REPORT

GL13XHC

Mini Hatchback 1.6 Cooper 3dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	14/03/2013	Keys	2	CAP Clean	£1,650.00
Year	2013	Service history	Yes	CAP Average	£1,250.00
Mileage	80,056 Miles Warranted	Service documents	Printout	CAP Below	£850.00
Fuel Type	PETROL	Number of stamps	8	Gearbox	MANUAL
Colour	BLUE	Last service date	03/03/2026	Gears	6
VIN	WMWSU32030T531328	Last service miles	77,935	Doors	3
Body Style	Hatchback	MOT Due	13/03/2027		

Last service 03/03/2026 at 77,935 miles- 8 services

Tyres

NSF	BUDGET	5.0mm
NSR	BUDGET	5.0mm
OSF	RAPID	6.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- PAS
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Central locking
- Rear wiper
- Electric door mirrors
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Remote central locking
- Service indicator
- Front fog lights
- Front head restraints
- Steering wheel reach adjustment
- Curtain airbags
- Rear airbags
- Cloth seat trim
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Drivers airbag
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Switches And Controls
Missing
Replace




2: Bonnet
Chipped
1 To 5



3: Bumper Front
Scratched
UpTo 25mm Thru Paint



4: Wheel nsf
Scratched
Over 50mm



5: Roof
Chipped
1 To 5



6: Door nsf
Dented
Over 30mm



7: Qtr Panel nsr
Dented
Over 30mm



8: Qtr Panel osr
Chipped
1 To 5



9: Wheel osr
Scratched
Over 50mm



10: Door osf
Dented
Over 30mm



11: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK