



VEHICLE INSPECTION REPORT

GX16FWZ

Hyundai IX20 1.6 CRDi Blue Drive SE 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
2

Details

Reg. date	12/03/2016	Body Style	MPV	Last service miles	65,931
Year	2016	Keys	2	MOT Due	17/03/2027
Mileage	68,869 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	DIESEL	Service documents	Service Book	Gears	6
Colour	BLUE	Number of stamps	10	Doors	5
VIN	TMAPU81SLGJ221518	Last service date	02/03/2026		

Last Service - 02.03.2026 at 65931 miles (10 services)

Tyres

NSF	YOKOHAMA	6.0mm
NSR	LAUFENN	5.0mm
OSF	YOKOHAMA	6.0mm
OSR	LAUFENN	4.0mm
Spare		

Features


- Bluetooth connection
- Body coloured bumpers
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Central locking
- Telephone
- Air conditioning
- Rear headrests
- Passenger airbag
- Remote central locking
- Radio/CD
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim

Photos






Condition Check



Damage Photos




1: Wheel osf
Corroded
Light




2: Door osf
Chipped
Edge Chip




3: Wheel osr
Corroded
Light




4: Door osr
Dented
2 Or Less UpTo 10mm



5: Wheel nsr
Corroded
Light



6: Door nsr
Dented
Over 2 UpTo 10mm



7: Wing nsf
Scratched
Over 25mm Thru Paint



8: Wheel nsf
Corroded
Light



9: Bumper Front
Scratched
25 to 100mm Thru Paint

10: Bonnet
Chipped
1 To 5

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK