



# VEHICLE INSPECTION REPORT

**SD12BXN**

## Vauxhall Corsa 1.2 SE 5dr

| Inspection      |    | Vehicle |         |
|-----------------|----|---------|---------|
| Serious Damage? | No | VAT     | Margin  |
|                 |    | V5      | Present |



### Details

|           |                         |                   |            |                    |            |
|-----------|-------------------------|-------------------|------------|--------------------|------------|
| Reg. date | 30/03/2012              | Body Style        | Hatchback  | Last service miles | 104,388    |
| Year      | 2012                    | Keys              | 1          | MOT Due            | 03/12/2026 |
| Mileage   | 106,111 Miles Warranted | Service history   | Yes        | Gearbox            | MANUAL     |
| Fuel Type | PETROL                  | Service documents | Printout   | Gears              | 5          |
| Colour    | GREY                    | Number of stamps  | 1          | Doors              | 5          |
| VIN       | W0L0SDL68C4177569       | Last service date | 30/09/2025 |                    |            |

LAST SERVICE 30/09/2025 @ 104,388 MILES (1 SERVICE) When left idling engine cuts out

Airbag light on

Car smokes

### Tyres

|       |             |       |
|-------|-------------|-------|
| NSF   | GOODYEAR    | 5.0mm |
| NSR   | GOODYEAR    | 5.0mm |
| OSF   | GOODYEAR    | 5.0mm |
| OSR   | CONTINENTAL | 5.0mm |
| Spare |             |       |

## Features


- Heated front seat
- Electric door mirrors
- Metallic Paint
- Central locking
- Alloy wheels
- Rear wiper
- Air conditioning
- ABS
- Remote central locking
- Radio/CD
- Front electric windows
- Drivers airbag
- Cloth seat trim
- Body coloured bumpers
- Rear headrests
- Passenger airbag
- Leather seat trim

## Photos





## Condition Check



## Damage Photos



1: Seat Base Cover nsf  
Torn  
Over 3mm




2: Door Pad nsf  
Torn  
Between 3mm + 10mm



3: Seat Base Cover osf  
Torn  
Over 3mm



4: Door osf  
Chipped  
Edge Chip



5: Door osr  
Chipped  
1 To 5



6: Bumper Rear  
Scratched  
Over 100mm Thru Paint



7: Tailgate  
Dented  
Over 30mm



8: Qtr Panel nsr  
Chipped  
1 To 5




9: Door nsr  
Scratched  
Over 25mm Thru Paint



10: Door nsf  
Chipped  
Multiple Chips



11: Wing nsf  
Dented  
2 Or Less UpTo 10mm



12: Bumper Front  
Scratched  
Over 100mm Thru Paint



13: Bonnet  
Chipped  
1 To 5

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Poor

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

|                          |       |                                                |       |
|--------------------------|-------|------------------------------------------------|-------|
| Engine Runs              | Fault | Gearbox 1st and Reverse Test                   | OK    |
| Brakes                   | OK    | Clutch Slip Test from Static                   | OK    |
| Parking Brake            | OK    | Gearbox Static Gear Selection (engine running) | OK    |
|                          |       | No Excessive Smoking                           | Fault |
| EML light illuminated    | OK    | Oil warning light illuminated                  | OK    |
| Airbag light illuminated | Fault | Service indicator light illuminated            | OK    |
| ABS light illuminated    | OK    |                                                |       |
| Windows                  | OK    | Radio                                          | OK    |
|                          |       | Steering                                       | OK    |