



VEHICLE INSPECTION REPORT

WN71VYD

Audi Q3 35 TFSI Black Edition 5dr S Tronic

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	15/11/2021	Body Style	Estate	Last service miles	34,460
Year	2021	Keys	2	MOT Due	06/10/2026
Mileage	35,097 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	PETROL	Service documents	Printout	Gears	7
Colour	WHITE	Number of stamps	3	Doors	5
VIN	WAUZZZF37N1028699	Last service date	17/06/2026		

£90 ADDITIONAL FEE

Last service 17/06/2026 at 34,460 miles- 3 main dealer services Tailgate faulty

Tyres

NSF	BUDGET	Damaged
NSR	HANKOOK	2.0mm
OSF	BUDGET	2.0mm
OSR	HANKOOK	2.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Rear wiper
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim
- Navigation system
- Steering wheel mounted controls
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- PAS
- Digital radio
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Tyre nsf
Damaged
Replace



2: Bonnet
Chipped
1 To 5



3: Bumper Front
Chipped
1 To 5




4: Wheel nsf
Scratched
Up To 50mm



5: Door nsf
Dented
Between 10mm + 30mm



6: Door nsr
Dented
Between 10mm + 30mm



7: Door nsr
Chipped
1 To 5



8: Bumper Rear
Scratched
25 to 100mm Thru Paint



9: Qtr Panel Arch Extension os
Scratched (Painted)
Over 25mm Thru Paint



10: Door osr
Chipped
1 To 5



11: Wheel osf
Scratched
Up To 50mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
 Additional fees may apply to some vendors.
 Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK