



VEHICLE INSPECTION REPORT

NC07SXD

Ford Focus 1.8 LX 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	30/06/2007	Keys	2	CAP Clean	£840.00
Year	2007	Service history	Yes	CAP Average	£430.00
Mileage	57,426 Miles Warranted	Service documents	Printout	CAP Below	£200.00
Fuel Type	PETROL	Number of stamps	3	Gearbox	MANUAL
Colour	SILVER	Last service date	23/05/2026	Gears	5
VIN	WF05XXGCD57E77466	Last service miles	57,140	Doors	5
Body Style	Hatchback	MOT Due	07/06/2027		

Last service 23/05/2026 at 57,140 miles- 3 services High clutch

Tyres

NSF	BUDGET	5.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Body coloured bumpers
- Rear headrests
- Passenger airbag
- Steel wheels
- Rear wiper
- Electric door mirrors
- Metallic Paint
- Central locking
- Telephone
- Air conditioning
- ABS
- Remote central locking
- Radio/CD
- Front electric windows
- Drivers airbag
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Door Moulding osf
Scratched (Painted)
UpTo 25mm Thru Paint



2: Door osf
Chipped
Edge Chip



3: Door osr
Dented
With Paint Damage



4: Bumper Rear
Scratched
Over 100mm Thru Paint



5: Tailgate
Scratched
UpTo 25mm Thru Paint




6: Qtr Panel nsr
Dented
Between 10mm + 30mm



7: Door Moulding nsr
Scratched (Painted)
Over 25mm Thru Paint



8: Door Moulding nsf
Scratched (Painted)
Over 25mm Thru Paint



9: Wing nsf
Dented
With Paint Damage



10: Bumper Front
Scratched
Over 100mm Thru Paint



11: Badgedecal Front
Missing
Replace



12: Bonnet
Chipped
1 To 5

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK