



VEHICLE INSPECTION REPORT

GX05UBA

Peugeot 206 SE

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	05/08/2005	Body Style	Hatchback	Last service miles	64,416
Year	2005	Keys	2	MOT Due	14/12/2026
Mileage	66,547 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	PETROL	Service documents	Service Book	Gears	4
Colour	BLUE	Number of stamps	16	Doors	5
VIN	VF32AKFWR44765814	Last service date	11/12/2024		

Last Service - 11.12.2024 at 64416 miles (16 services)

Tyres

NSF	SAILUN	5.0mm
NSR	FALKEN	5.0mm
OSF	SAILUN	5.0mm
OSR	FALKEN	5.0mm
Spare		

Features


- Rear wiper
 - Air conditioning
 - Metallic Paint
 - Central locking
- Radio/CD
 - Climate control
 - ABS
 - Remote central locking
- Body coloured bumpers
 - Front electric windows
 - Drivers airbag
 - Cloth seat trim
- Electric door mirrors
 - Rear headrests
 - Passenger airbag
 - Alloy wheels

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm




2: Wing osf
Dented
Over 30mm




3: Door osf
Chipped
1 To 5



4: Sill os
Rusted
Over 5mm



5: Door osf
Chipped
Edge Chip



6: Door osr
Dented
Between 10mm + 30mm



7: Qtr Panel osr
Poor Previous Repair
Poor Paint



8: Bumper Rear
Scratched
Over 100mm Thru Paint



9: Qtr Panel nsr
Chipped
1 To 5




10: Wheel nsr
Scratched
Over 50mm



11: Door nsr
Chipped
1 To 5



12: Sill ns
Scratched
Over 25mm Thru Paint



13: Door nsf
Chipped
Multiple Chips




14: Wheel nsf
Scratched
Over 50mm



15: Wing nsf
Dented
Between 10mm + 30mm



16: Bumper Front
Scratched
Over 100mm Thru Paint



17: Bonnet
Chipped
1 To 5



18: C Post os
Poor Previous Repair
Paint Flake

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK