



VEHICLE INSPECTION REPORT

GV13AZN

Ford Fiesta 1.0 EcoBoost Zetec 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	29/06/2013	Body Style	Hatchback	Last service miles	86,286
Year	2013	Keys	1	MOT Due	24/06/2027
Mileage	87,083 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Service Book	Gears	5
Colour	WHITE	Number of stamps	9	Doors	5
VIN	WF0DXXGAKDDR75309	Last service date	09/06/2026		

£100 ADDITIONAL FEE

last service 9/6/26 @ 86,286 miles (9 services 2 main dealer) book & print


Tyres



NSF	BUDGET	5.0mm
NSR	UNIROYAL	5.0mm
OSF	BUDGET	5.0mm
OSR	UNIROYAL	5.0mm
Spare		

Features


- Bluetooth connection
- Radio/CD
- Front electric windows
- Drivers airbag
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Rear wiper
- Electric door mirrors
- Solid Paint
- Traction control
- Alloy wheels
- Telephone
- Air conditioning
- ABS
- Central locking

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Door osr
Chipped
1 To 5



3: Qtr Panel osr
Dented
Over 30mm




4: Bumper Rear
Poor Previous Repair
Paint Flake



5: Qtr Panel nsr
Dented
Between 10mm + 30mm



6: Door nsr
Dented
Over 30mm




7: Door nsf
Chipped
1 To 5



8: Wheel nsf
Scratched
Over 50mm



9: Bumper Front
Scratched
Over 100mm Thru Paint



10: Bonnet
Chipped
1 To 5



11: Roof
Chipped
1 To 5

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK