



VEHICLE INSPECTION REPORT

VU05DBV

Volkswagen Golf 2.0T GTI 3dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	01/03/2005	Body Style	Hatchback	Last service miles	122,060
Year	2005	Keys	2	MOT Due	06/04/2027
Mileage	129,979 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Service Book	Gears	6
Colour	BLACK	Number of stamps	13	Doors	3
VIN	WVWZZZ1KZ5W201749	Last service date	26/03/2025		

£90 ADDITIONAL FEE

Last Service - 26.03.2025 at 122060 miles (13 services)

Cambelt and Water Pump Replaced 23.02.2023 @ 102619 Miles Oil leak

Car goes into limp mode

Tyres


NSF	LAUFENN	4.0mm
NSR	LAUFENN	5.0mm
OSF	LAUFENN	3.0mm
OSR	LAUFENN	5.0mm
Spare		

Features


- Rear wiper
- Electric sunroof
- Front electric windows
- Drivers airbag
- Central locking
- Radio/CD
- Air conditioning
- Rear headrests
- Passenger airbag
- Remote central locking
- Body coloured bumpers
- Climate control
- Metallic Paint
- Traction control
- Leather seat trim
- Electric door mirrors
- Front armrest
- ABS
- Tyre pressure monitor
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Seat Back Cover osf
Holed
Over 3mm



2: Wheel osf
Scratched
Over 50mm



3: Qtr Panel osr
Poor Previous Repair
Poor Paint



4: Door osf
Chipped
Edge Chip



5: Wheel osr
Scratched
Over 50mm



6: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm



7: Bumper Rear
Scratched
25 to 100mm Thru Paint



8: Tailgate
Dented
2 Or Less UpTo 10mm




9: Qtr Panel nsr
Rusted
Over 5mm



10: Wheel nsr
Corroded
Light



11: Door nsf
Chipped
Edge Chip



12: Door nsf
Chipped
1 To 5



13: Wing nsf
Chipped
1 To 5



14: Wheel nsf
Scratched
Over 50mm



15: Bumper Front
Chipped
Multiple Chips



16: Bonnet
Dented
Over 30mm



17: Screen Front
Cracked
Replace



18: Door osf
Rusted
UpTo 5mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK