

# VEHICLE INSPECTION REPORT

**SG03UML**

## Nissan X-Trail 2.2 dCi 136 SVE 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	17/03/2003	Colour	SILVER	Service history	None
Year	2003	VIN	JN1TENT30U0035578	MOT Due	03/11/2025
Mileage	131,175 Miles Warranted	Body Style	Estate	Gearbox	MANUAL
Fuel Type	Diesel	Keys	2	Gears	6

No Service History No headrests


### Tyres

NSF	BUDGET	2.0mm
NSR	BUDGET	4.0mm
OSF	BUDGET	2.0mm
OSR	NEXEN	3.0mm
Spare		

## Features


- PAS
- Body coloured bumpers
- Air conditioning
- Front head restraints
- ABS
- Central locking
- Rear wiper
- Electric door mirrors
- Climate control
- Rear electric windows
- Drivers airbag
- Remote central locking
- Steering wheel mounted controls
- Electric sunroof
- Front armrest
- Metallic Paint
- Isofix child seat anchor points
- Leather seat trim
- Radio/Cassette
- Opening panoramic glass roof
- Front electric windows
- 3x3 point rear seat belts
- Passenger airbag
- Alloy wheels

## Photos






## Condition Check



## Damage Photos



1: Bumper Rear  
Scratched  
Over 100mm Thru Paint



2: Boot Lid  
Scratched  
Over 25mm Not Thru Paint





3: Wheel osr  
Scratched  
Over 50mm



4: Qtr Panel osr  
Rusted  
Over 5mm



5: Door osr  
Rusted  
UpTo 5mm



6: Door osf  
Rusted  
UpTo 5mm



7: Wing osf  
Scratched  
Over 25mm Not Thru Paint



8: Wheel osf  
Scratched  
Over 50mm



9: Bumper Front  
Scratched  
Over 100mm Thru Paint



10: Bonnet  
Chipped  
1 To 5




11: Wing nsf  
Chipped  
1 To 5



12: Wheel nsf  
Scratched  
Over 50mm



13: Door nsf  
Dented  
With Paint Damage



14: Door nsr  
Scratched  
Over 25mm Not Thru Paint





15: Door nsr  
Chipped  
1 To 5



16: Qtr Panel nsr  
Rusted  
Over 5mm



17: Wheel nsr  
Scratched  
Over 50mm



18: Screen Front  
Chipped  
UpTo 10mm



19: Seat Back Cover osf  
Torn  
Over 3mm



20: Seat Base Cover osf  
Torn  
Over 3mm



21: Seat Base Cover nsf  
Scuffed  
Over 25mm

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Poor

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	Fault
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK