



VEHICLE INSPECTION REPORT

FE18UJL

Toyota Avensis 1.8 Active 5dr CVT Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	12/03/2018	Body Style	Estate	Last service miles	120,436
Year	2018	Keys	2	MOT Due	25/08/2026
Mileage	130,014 Miles Warranted	Service history	Yes	Gearbox	CVT
Fuel Type	PETROL	Service documents	Service Book	Gears	1
Colour	BLUE	Number of stamps	8	Doors	5
VIN	SB1EG76L30E154222	Last service date	08/01/2026		

last service 8/1/26 @ 120,436 miles (8 services 4 main dealer) Ex taxi

Tyres

NSF	BUDGET	5.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	6.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Steering wheel mounted controls
- Space saver spare wheel
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Cloth seat trim
- PAS
- Radio/CD
- Air conditioning
- Front head restraints
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Steel wheels
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Metallic Paint
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Poor Previous Repair
Paint Flake



3: Wing nsf
Scratched
Over 25mm Thru Paint



4: Door nsf
Chipped
1 To 5



5: Door nsf
Chipped
Edge Chip



6: Door nsr
Chipped
1 To 5




7: Qtr Panel nsr
Poor Previous Repair
Rippled UpTo 30%




8: Bumper Rear
Scratched
Over 100mm Thru Paint



9: Qtr Panel osr
Chipped
1 To 5



10: Door osr
Chipped
1 To 5



11: Door osf
Scratched
Over 25mm Thru Paint



12: Wing osf
Poor Previous Repair
Paint Flake

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK