



# VEHICLE INSPECTION REPORT

**E011GBE**

## Nissan Juke 1.6 DiG-T Tekna 5dr

| Inspection      |    | Vehicle |         |
|-----------------|----|---------|---------|
| Serious Damage? | No | VAT     | Margin  |
|                 |    | V5      | Present |



### Details

|           |                           |                   |              |                    |            |
|-----------|---------------------------|-------------------|--------------|--------------------|------------|
| Reg. date | 12/03/2011                | Body Style        | Hatchback    | Last service miles | 64,498     |
| Year      | 2011                      | Keys              | 2            | MOT Due            | 19/01/2027 |
| Mileage   | 79,252 Miles<br>Warranted | Service history   | Yes          | Gearbox            | MANUAL     |
| Fuel Type | PETROL                    | Service documents | Service Book | Gears              | 6          |
| Colour    | WHITE                     | Number of stamps  | 10           | Doors              | 5          |
| VIN       | SJNFAAF15U6061923         | Last service date | 26/09/2023   |                    |            |

£90 ADDITIONAL FEE

LAST SERVICE 26/09/2023 @ 64,498 MILES (10 SERVICES) Engine noisy , car shaking when idle  
Steering knocking noisy when turning

### Tyres

|       |        |       |
|-------|--------|-------|
| NSF   | FALKEN | 5.0mm |
| NSR   | BUDGET | 5.0mm |
| OSF   | FALKEN | 5.0mm |
| OSR   | BUDGET | 5.0mm |
| Spare |        |       |

## Features


- Bluetooth connection
- Park assist camera
- Digital radio
- Front fog lights
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Central locking
- Cruise control
- PAS
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Remote central locking
- Heated front seat
- Rear wiper
- Body coloured bumpers
- Folding rear seats
- Rear electric windows
- Solid Paint
- Passenger airbag
- Leather seat trim
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Side airbags
- Alloy wheels

## Photos





## Condition Check



## Damage Photos



1: Seat Base Cover osf  
Torn  
Over 3mm



2: Bumper Front  
Poor Previous Repair  
Poor Paint



3: Other  
N/A  
N/A



4: Bonnet  
Chipped  
1 To 5



5: Wheel nsf  
Scratched  
Over 50mm



6: Wing nsf  
Chipped  
1 To 5



7: A Post ns  
Chipped  
1 To 5



8: Door nsf  
Dented  
Between 10mm + 30mm



9: Door nsr  
Dented  
With Paint Damage




10: Wheel nsr  
Scratched  
Over 50mm



11: Qtr Panel nsr  
Dented  
2 Or Less UpTo 10mm



12: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



13: Qtr Panel osr  
Dented  
2 Or Less UpTo 10mm



14: Door osr  
Dented  
Between 10mm + 30mm



15: Door osr  
Chipped  
Edge Chip



16: Door osf  
Dented  
2 Or Less UpTo 10mm



17: Door osf  
Chipped  
Edge Chip



18: Door osr  
Scratched  
UpTo 25mm Thru Paint



19: Wing osf  
Scratched  
Over 25mm Thru Paint



20: Wheel osf  
Scratched  
Over 50mm



21: Roof  
Chipped  
1 To 5

Interior

|                  |         |                      |         |
|------------------|---------|----------------------|---------|
| Carpet Condition | Average | Upholstery Condition | Average |
| Seat Condition   | Average | Odour                | No      |

Vehicle Inspection Report

**Disclaimer**  
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.  
Additional fees may apply to some vendors.  
Please note buyers rate increase from 01/01/2025

|                          |       |                                                |    |
|--------------------------|-------|------------------------------------------------|----|
| Engine Runs              | Fault | Gearbox 1st and Reverse Test                   | OK |
| Brakes                   | OK    | Clutch Slip Test from Static                   | OK |
| Parking Brake            | OK    | Gearbox Static Gear Selection (engine running) | OK |
|                          |       | No Excessive Smoking                           | OK |
| EML light illuminated    | OK    | Oil warning light illuminated                  | OK |
| Airbag light illuminated | OK    | Service indicator light illuminated            | OK |
| ABS light illuminated    | OK    |                                                |    |
| Windows                  | OK    | Radio                                          | OK |
| Sat nav                  | OK    | Steering                                       | OK |