



VEHICLE INSPECTION REPORT

AU62UBK

Ford Kuga 2.0 TDCi 140 Titanium X 5dr 2WD

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	13/09/2012	Body Style	Estate	Last service miles	85,650
Year	2012	Keys	3	MOT Due	18/06/2027
Mileage	86,505 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	DIESEL	Service documents	Service Book	Gears	6
Colour	WHITE	Number of stamps	14	Doors	5
VIN	WF0RXXGCDRCE00966	Last service date	28/05/2026		

CAMBELT & WATER PUMP REPLACED 07/06/2022
LAST SERVICE 28/05/2026 @ 85,650 MILES (14 SERVICES)

Tyres

NSF	PIRELLI	5.0mm
NSR	PIRELLI	6.0mm
OSF	PIRELLI	5.0mm
OSR	PIRELLI	6.0mm
Spare		


Features

- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Electrically adjustable drivers seat
- Rear headrests
- Passenger airbag
- Leather seat trim
- Front parking sensor
- Telephone
- Fixed panoramic glass roof
- Front armrest
- Solid Paint
- Traction control
- Alloy wheels
- Heated front seat
- Radio/CD
- Air conditioning
- Front electric windows
- ABS
- Central locking
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Rear electric windows
- Drivers airbag
- Remote central locking


Photos



Condition Check



Damage Photos



1: Wing osf
Poor Previous Repair
Poor Paint



2: Door osf
Chipped
Edge Chip



3: Wheel osr
Corroded
Light



4: Wheel nsr
Corroded
Light



5: Other
N/A
N/A

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK