

# VEHICLE INSPECTION REPORT

**YR60KAU**

## Ford Focus 2.0 Zetec S 3dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**3**

### Details

Reg. date	29/09/2010	VIN	WF0GXXGCDGAB18907	CAP Average	£970.00
Year	2010	Body Style	Hatchback	CAP Below	£575.00
Mileage	88,333 Miles Warranted	Keys	1	Gearbox	MANUAL
Fuel Type	Petrol	MOT Due	01/09/2025	Gears	5
Colour	WHITE	CAP Clean	£1,375.00	Doors	3

£100 ADDITIONAL FEE. Tapping noise/ intermittent noise from exhaust


### Tyres

NSF	RAPID	4.0mm
NSR	BUDGET	3.0mm
OSF	SUNNY	4.0mm
OSR	NEXEN	3.0mm
Spare		

## Features


- PAS
- Radio/CD
- Climate control
- Rear headrests
- Drivers airbag
- Central locking
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Solid Paint
- Isofix child seat anchor points
- Remote central locking
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- ABS
- Side airbags
- Alloy wheels

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Chipped  
Multiple Chips





3: Wheel nsf  
Scratched  
Over 50mm



4: Door nsf  
Chipped  
1 To 5




5: Qtr Panel nsr  
Rusted  
UpTo 5mm



6: Wheel nsr  
Scratched  
Over 50mm



7: Bumper Rear  
Scratched  
Over 100mm Thru Paint



8: Boot Lid  
Scratched  
Over 25mm Not Thru Paint



9: Wheel osr  
Scratched  
Over 50mm



10: Qtr Panel osr  
Rusted  
UpTo 5mm



11: Door osf  
Dented  
2 Or Less UpTo 10mm



12: Door Mirror Assy osf  
Broken  
Replace



13: Wheel osf  
Scratched  
Over 50mm



14: Wing osf  
Chipped  
1 To 5

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK