



VEHICLE INSPECTION REPORT

GY66ZNV

Toyota Aygo 1.0 VVT-i X-Play 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	20/01/2017	Body Style	Hatchback	Last service miles	39,585
Year	2017	Keys	2	MOT Due	19/01/2027
Mileage	111,715 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Printout	Gears	5
Colour	RED	Number of stamps	3	Doors	5
VIN	JTDKGNEC50N231080	Last service date	30/05/2019		

last service 30/5/19 @ 39,585 miles (3 main dealer)


Tyres

NSF	BUDGET	3.0mm
NSR	AVON	4.0mm
OSF	BUDGET	3.0mm
OSR	AVON	4.0mm
Spare		

Features


- Bluetooth connection
- Telephone
- Air conditioning
- ABS
- Tyre pressure monitor
- Steel wheels
- Cruise control
- Radio/CD
- Front electric windows
- Drivers airbag
- Central locking
- Park assist camera
- Body coloured bumpers
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear wiper
- Electric door mirrors
- Solid Paint
- Traction control
- Cloth seat trim

Photos






Condition Check



Damage Photos



1: Wing osf
Scratched
UpTo 25mm Thru Paint




2: Door osf
Scratched
Over 25mm Thru Paint



3: Door osr
Chipped
1 To 5



4: Other
N/A
N/A



5: Other
N/A
N/A




6: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



7: Bumper Rear
Scratched
Up To 25mm Thru Paint



8: Qtr Panel nsr
Chipped
1 To 5



9: Other
N/A
N/A




10: Door nsf
Dented
With Paint Damage




11: Other
N/A
N/A



12: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



13: Bonnet
Chipped
Multiple Chips



14: Bumper Front
Chipped
Multiple Chips



15: A Post os
Chipped
1 To 5

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK