



VEHICLE INSPECTION REPORT

RO14RYJ

Nissan Juke 1.6 N-Tec 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	14/04/2014	Body Style	Hatchback	Last service miles	69,867
Year	2014	Keys	2	MOT Due	03/08/2027
Mileage	69,878 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Service Book	Gears	5
Colour	RED	Number of stamps	11	Doors	5
VIN	SJNFBAF15U6505188	Last service date	16/07/2026		

last service 16/7/26 @ 69,867 miles (11 main dealer)

Tyres


NSF	KUMHO	5.0mm
NSR	KUMHO	5.0mm
OSF	KUMHO	5.0mm
OSR	KUMHO	5.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Body coloured bumpers
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Rear wiper
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Park assist camera
- Digital radio
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Wheel osf
Corroded
Light




2: Wing osf
Poor Previous Repair
Poor Paint



3: Door osf
Poor Previous Repair
Paint Flake




4: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



5: Door osr
Chipped
1 To 5



6: Wheel osr
Corroded
Light



7: Tailgate
Chipped
1 To 5



8: Bumper Rear
Scratched
25 to 100mm Thru Paint



9: Wheel nsr
Corroded
Light



10: Qtr Panel nsr
Dented
2 Or Less UpTo 10mm



11: Qtr Panel nsr
Chipped
1 To 5



12: Door nsr
Chipped
1 To 5



13: Door nsr
Chipped
Edge Chip



14: Wing nsf
Chipped
1 To 5



15: Wheel nsf
Corroded
Light



16: Bumper Front
Chipped
1 To 5



17: Bumper Front
Scratched
UpTo 25mm Thru Paint



18: Bonnet
Chipped
1 To 5



19: Door Mirror Glass ns
Broken
Replace

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK