



VEHICLE INSPECTION REPORT

GX17PYS

Vauxhall Movano 2.3 CDTI H2 Van 130ps

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present



Details

Reg. date	01/03/2017	Body Style	Panel Van	Last service miles	125,046
Year	2017	Keys	2	MOT Due	09/04/2027
Mileage	149,753 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Printout	Gears	6
Colour	WHITE	Number of stamps	6		
VIN	W0LMRY603HB125036	Last service date	06/11/2024		

last service 6/11/24 @ 125,046 miles (6 services) Radio coded unable to check all features
Side door will not open

Tyres

NSF	NEXEN	Damaged
NSR	NEXEN	5.0mm
OSF	FALKEN	Damaged
OSR	AVON	5.0mm
Spare		

Features


- Digital radio
- Air conditioning
- Front electric windows
- Drivers airbag
- Central locking
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Seat Base Cover osf
Scuffed
Over 25mm



2: Bonnet
Dented
Over 30mm



3: Front TowEye Cvr
Missing
Replace



4: Screen Front
Cracked
Replace



5: Sill ns
Dented
With Paint Damage



6: Door Mirror Assy nsf
Broken
Replace



7: Door nsf
Chipped
Edge Chip



8: B Post ns
Dented
Between 10mm + 30mm




9: Door nsr
Dented
Over 30mm



10: Qtr Panel nsr
Dented
With Paint Damage



11: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm




12: D Post ns
Dented
With Paint Damage



13: Tailgate
Dented
Over 30mm



14: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm



15: Roof
Dented
Over 30mm



16: Qtr Panel osr
Dented
With Paint Damage



17: Panel Front
Scratched
UpTo 25mm Thru Paint



18: Door osf
Dented
With Paint Damage



19: Door Mirror Assy osf
Broken
Replace



20: Fascia Trim
Missing
Replace



21: Tyre osf
Damaged
Replace



22: Tyre nsf
Damaged
Replace



23: Seat Base Cover nsf
Holed
Over 3mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	Fault
		Steering	OK