



VEHICLE INSPECTION REPORT

FE13GFZ

Kia Picanto 1.0 City 3dr

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 Present

nama
GRADE
3

Details

Reg. date 21/03/2013

Year 2013

Mileage 55,326 Miles
Warranted

Fuel Type PETROL

Colour SILVER

VIN KNABX311LDT481880

Body Style Hatchback

Keys 2

Service history Yes

Service documents Service Book

Number of stamps 11

Last service date 21/10/2025

Last service miles 52,755

MOT Due 27/10/2026

Gearbox MANUAL

Gears 5

Doors 3

last service 21/10/25 @ 52,755 miles (11 services 5 main dealer)

Tyres

NSF AUTOGREEN 5.0mm

NSR LAUFENN 6.0mm

OSF NEXEN 5.0mm


OSR HANKOOK 6.0mm

Spare

Features


- Bluetooth connection
- Body coloured bumpers
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Rear parking sensor
- Electric door mirrors
- Metallic Paint
- Traction control
- Alloy wheels
- Rear wiper
- Air conditioning
- ABS
- Central locking
- Radio/CD
- Front electric windows
- Drivers airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Scratched
UpTo 25mm Thru Paint



3: Door osf
Dented
Over 30mm



4: Wheel osr
Scratched
Over 50mm




5: Tailgate
Scratched
Over 25mm Thru Paint



6: Wheel nsr
Scratched
Over 50mm



7: Wheel nsf
Scratched
Over 50mm



8: Bumper Front
Scratched
Over 100mm Thru Paint



9: Bonnet
Chipped
1 To 5

10: Carpets Front
Holed
Over 3mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK