



VEHICLE INSPECTION REPORT

SD710XR

BMW 5 Series 520d xDrive MHT M Sport 4dr Step Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	09/12/2021	Body Style	Saloon	Last service miles	60,500
Year	2021	Keys	2	MOT Due	08/12/2026
Mileage	62,630 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Electric Diesel	Service documents	Electronic & Paper	Gears	8
Colour	BLUE	Number of stamps	2	Doors	4
VIN	WBA52BL0X0WX53990	Last service date	29/04/2026		

£90 ADDITIONAL FEE

Last service 29/04/2026 at 60,500 miles- 2 services (1 main dealer service) Recorded on on-board system and printout

Tyres

NSF	CONTINENTAL	5.0mm
NSR	BRIDGESTONE	5.0mm
OSF	CONTINENTAL	5.0mm
OSR	BRIDGESTONE	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Cruise control
- Park assist camera
- Body coloured bumpers
- Electrically adjustable drivers seat
- Metallic Paint
- Traction control
- Leather seat trim
- Front parking sensor
- Rear parking sensor
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Heated front seat
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Poor Previous Repair
Poor Paint



3: Wheel nsf
Scratched
Up To 50mm




4: Screen Front
Chipped
UpTo 10mm




5: Door nsr
Chipped
1 To 5



6: Wheel nsr
Scratched
Up To 50mm



7: Bumper Rear
Poor Previous Repair
Poor Paint



8: Qtr Panel osr
Poor Previous Repair
Rippled UpTo 30%



9: Door osr
 Scratched
 UpTo 25mm Thru Paint



10: Door osf
 Chipped
 1 To 5



11: Wing osf
 Scratched
 UpTo 25mm Thru Paint



12: Wheel osf
 Scratched
 Up To 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
 Additional fees may apply to some vendors.
 Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK