



VEHICLE INSPECTION REPORT

GY59FHX

Ford Fiesta 1.25 Zetec 5dr [82]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	28/09/2009	Body Style	Hatchback	Last service miles	130,685
Year	2009	Keys	2	MOT Due	16/08/2026
Mileage	140,368 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Service Book	Gears	5
Colour	BLUE	Number of stamps	11	Doors	5
VIN	WF0JXXWPJJ9A25405	Last service date	13/08/2024		

£100 ADDITIONAL FEE

Last service 13/08/2024 at 130,685 miles- 11 services (3 main dealer)
Timing belt replaced 07/01/2022 at 114,184 miles Radio does not turn on

Tyres

NSF	KUMHO	5.0mm
NSR	DOUBLESTAR	4.0mm
OSF	TRIANGLE	6.0mm
OSR	WESTLAKE	5.0mm
Spare		

Features


- Bluetooth connection
- Body coloured bumpers
- Rear headrests
- Passenger airbag
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Metallic Paint
- Central locking
- Telephone
- Air conditioning
- ABS
- Remote central locking
- Radio/CD
- Front electric windows
- Drivers airbag
- Cloth seat trim

Photos






Condition Check



Damage Photos



1: Wing of
Dented
With Paint Damage



2: Door of
Chipped
1 To 5



3: Door osf
Chipped
Edge Chip



4: Door osr
Chipped
1 To 5



5: Qtr Panel osr
Dented
With Paint Damage



6: Wheel osr
Scratched
Over 50mm



7: Wheel osf
Scratched
Up To 50mm



8: Bumper Rear
Scratched
Over 100mm Thru Paint



9: Tailgate
Dented
Over 30mm



10: Wheel nsr
Scratched
Over 50mm



11: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



12: Door nsr
Dented
2 Or Less UpTo 10mm



13: Door nsr
Chipped
1 To 5



14: Door nsf
Dented
With Paint Damage



15: Wheel nsf
Scratched
Over 50mm



16: Bumper Front
Poor Previous Repair
Paint Flake



17: Bonnet
Chipped
1 To 5



18: C Post os
Dented
With Paint Damage



19: Sill os
Rusted
Over 5mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	Fault
		Steering	OK