



VEHICLE INSPECTION REPORT

DC63AVE

Volkswagen Golf 1.6 TDI 110 BlueMotion 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	17/02/2014	Body Style	Hatchback	Last service miles	90,418
Year	2014	Keys	2	MOT Due	27/02/2027
Mileage	92,369 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	DIESEL	Service documents	Service Book	Gears	6
Colour	BLACK	Number of stamps	9	Doors	5
VIN	WVVZZZAUZEW268091	Last service date	16/02/2026		

£90 ADDITIONAL FEE

Last service 16/02/2026 at 90,418 miles- 9 services

Tyres


NSF	APOLLO	5.0mm
NSR	LAUFENN	5.0mm
OSF	APOLLO	5.0mm
OSR	LAUFENN	5.0mm
Spare		

Features


- Bluetooth connection
- Body coloured bumpers
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear wiper
- Electric door mirrors
- Metallic Paint
- Traction control
- Cloth seat trim
- Telephone
- Air conditioning
- ABS
- Tyre pressure monitor
- Alloy wheels
- Radio/CD
- Front electric windows
- Drivers airbag
- Central locking

Photos






Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Scratched
Over 25mm Thru Paint



3: Sill os
Scratched
Over 25mm Thru Paint



4: Door osf
Chipped
Edge Chip



5: Door osr
Chipped
1 To 5



6: Bumper Rear
Scratched
Over 100mm Thru Paint



7: Wheel nsr
Scratched
Up To 50mm



8: Door nsf
Chipped
1 To 5



9: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



10: Wheel nsf
Scratched
Over 50mm



11: Wing nsf
Chipped
1 To 5



12: Bumper Front
Scratched
Over 100mm Thru Paint



13: Bonnet
Chipped
Multiple Chips

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK