



VEHICLE INSPECTION REPORT

EO68BZR

Citroen Grand C4 Spacetourer 2.0 BlueHDi 160 Feel 5dr EAT8

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	01/09/2018	Body Style	MPV	Last service miles	138,881
Year	2018	Keys	2	MOT Due	01/09/2026
Mileage	139,163 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Diesel	Service documents	Service Book	Gears	8
Colour	WHITE	Number of stamps	8		
VIN	VF73AEHYRJ724346	Last service date	01/06/2026		

Last service 01/06/2026 at 138,881 miles- 8 main dealer services

Tyres

NSF	WESTLAKE	5.0mm
NSR	SUNNY	5.0mm
OSF	WESTLAKE	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Front parking sensor
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Solid Paint
- Traction control
- Cloth seat trim
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking

Photos





Condition Check




Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Chipped
1 To 5



3: A Post os
Dented
With Paint Damage



4: Door osf
Dented
Between 10mm + 30mm



5: Door osf
Chipped
Edge Chip



6: Door osr
Scratched
UpTo 25mm Thru Paint



7: Wheel osr
Corroded
Light



8: Bumper Rear
Scratched
Over 100mm Thru Paint



9: Qtr Panel nsr
Dented
With Paint Damage



10: Wheel nsr
Corroded
Light



11: Door nsr
Dented
With Paint Damage



12: Door nsf
Chipped
Edge Chip



13: Wheel nsf
Scratched
Over 50mm



14: Bumper Front
Scratched
25 to 100mm Thru Paint



15: Bonnet
Chipped
1 To 5

16: Qtr Panel osr
Dented
Over 30mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK