



VEHICLE INSPECTION REPORT

EF21UKU

Volkswagen Id.3 150kW Tech Pro Performance 58kWh 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	25/06/2021	Body Style	Hatchback	MOT Due	24/06/2027
Year	2021	Keys	2	Gearbox	AUTOMATIC
Mileage	70,694 Miles Warranted	Service history	Yes	Gears	1
Fuel Type	ELECTRICITY	Number of stamps	2	Doors	5
Colour	WHITE	Last service date	31/05/2025		
VIN	VWVZZZE1ZMP067091	Last service miles	60,107		

£90.00 ADDITIONAL FEE
NO SERVICE


Tyres

NSF	GOODYEAR	5.0mm
NSR	GOODYEAR	5.0mm
OSF	GOODYEAR	4.0mm
OSR	GOODYEAR	6.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Telephone
- Fixed panoramic glass roof
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim
- Cruise control
- Park assist camera
- Radio/CD
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Heated front seat
- Rear wiper
- Electric door mirrors
- Front armrest
- Solid Paint
- Traction control
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Up To 50mm



2: Door osf
Chipped
Edge Chip



3: Door osr
Chipped
Edge Chip



4: Bumper Rear
Scratched
25 to 100mm Thru Paint



5: Bumper Rear
Chipped
Multiple Chips



6: Wheel nsr
Scratched
Over 50mm



7: Door nsr
Chipped
Edge Chip



8: Wheel nsf
Scratched
Over 50mm



9: Bumper Front
Scratched
25 to 100mm Thru Paint



10: Bumper Front
Chipped
Multiple Chips



11: Bonnet
Chipped
1 To 5



12: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		