



VEHICLE INSPECTION REPORT

EK19PBO

Kia Sportage 1.6T GDi ISG 4 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	01/03/2019	Body Style	Estate	Last service miles	64,978
Year	2019	Keys	2	MOT Due	Expired
Mileage	97,000 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Service Book	Gears	6
Colour	GREY	Number of stamps	6	Doors	5
VIN	U5YPH816LKL638400	Last service date	28/02/2025		

£100 ADDITIONAL FEE

MOT EXPIRED

Last Service - 28.02.2025 at 64978 miles (6 services)

Tyres

NSF	BRIDGESTONE	5.0mm
NSR	NEXEN	5.0mm
OSF	BRIDGESTONE	5.0mm
OSR	MICHELIN	5.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Radio/CD
- Air conditioning
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Heated front seat
- Rear wiper
- Electric door mirrors
- Electrically adjustable drivers seat
- Rear electric windows
- Drivers airbag
- Central locking
- Navigation system
- Telephone
- Electric sunroof
- Electrically adjustable passenger seat
- Rear headrests
- Passenger airbag
- Remote central locking

Photos







Condition Check



Damage Photos



1: Wheel osf
Corroded
Light



2: Door osf
Chipped
1 To 5




3: Door osr
Chipped
1 To 5




4: Door osr
Dented
2 Or Less UpTo 10mm



5: Wheel osr
Corroded
Light



6: Bumper Rear
Chipped
1 To 5



7: Wheel nsr
Corroded
Light



8: Door nsr
Chipped
1 To 5



9: Door nsf
Chipped
Edge Chip



10: Wheel nsf
Corroded
Light



11: Bumper Front
Scratched
25 to 100mm Thru Paint



12: Bonnet
Chipped
1 To 5

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	Fault
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	Fault
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		