



VEHICLE INSPECTION REPORT

YP14KYN

Mercedes-Benz C Class C220 BlueTEC AMG Line 4dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	01/08/2014	Body Style	Saloon	Last service miles	66,772
Year	2014	Keys	2	MOT Due	07/07/2027
Mileage	105,976 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	DIESEL	Service documents	Printout	Gears	7
Colour	SILVER	Number of stamps	3	Doors	4
VIN	WDD2050042F049974	Last service date	29/09/2021		

last service 29/9/21 @ 66,772 miles (3 services 1 main dealer) Oil leak
Eml light is on


Tyres


NSF	NEXEN	6.0mm
NSR	PIRELLI	7.0mm
OSF	NEXEN	6.0mm
OSR	PIRELLI	7.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- 3x3 point rear seat belts
- Cruise control
- Park assist camera
- ABS
- Front parking sensor
- PAS
- Curtain airbags
- Heated front seat
- Rear parking sensor
- Drivers airbag

Photos






Condition Check



Damage Photos



1: Other
N/A
N/A



2: Seat Base Cover osf
Torn
Over 3mm



3: Seat Back Cover osf
Burn
Over 3mm




4: Seat Back Cover osf
Torn
Over 3mm



5: Bonnet
Poor Previous Repair
Poor Paint



6: Bumper Front
Hole
Over 25mm



7: Wheel nsf
Scratched
Over 50mm



8: Flasher Side Repeater ns
Broken
Replace



9: Wing nsf
Scratched
Over 25mm Thru Paint



10: Door nsf
Chipped
1 To 5



11: Door nsr
Scratched
Over 25mm Thru Paint



12: Wheel nsr
Scratched
Over 50mm



13: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



14: Bumper Rear
Poor Previous Repair
Poor Paint



15: Qtr Panel osr
Scratched
Over 25mm Thru Paint



16: Wheel osr
Scratched
Over 50mm



17: Door osr
Dented
With Paint Damage



18: Door osf
Dented
With Paint Damage



19: Screen Front
Chipped
Over 10mm



20: Wheel osf
Scratched
Over 50mm



21: Wing osf
 Poor Previous Repair
 Poor Paint

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Poor	Odour	No

Vehicle Inspection Report

Disclaimer
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
 Additional fees may apply to some vendors.
 Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK