



VEHICLE INSPECTION REPORT

GV15NHK

Volvo XC60 D4 [181] R DESIGN 5dr AWD Geartronic

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 Present

nama
GRADE
3

Details

Reg. date	30/06/2015	Body Style	Estate	Last service miles	118,546
Year	2015	Keys	1	MOT Due	18/11/2026
Mileage	154,757 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	GREY	Number of stamps	9	Doors	5
VIN	YV1DZ8156F2691367	Last service date	14/11/2023		

£90 ADDITIONAL FEE

LAST SERVICE 14/11/2023 @ 118,546 MILES (9 SERVICES)

CAMBELT & WATER PUMP REPLACED 07/03/2023 EML light on car has been plugged in and detects mass or volume air flow a circuit range

Tyres

NSF	KUMHO	4.0mm
NSR	KUMHO	5.0mm
OSF	KUMHO	4.0mm
OSR	KUMHO	5.0mm
Spare		

Features


- Bluetooth connection
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Wheel osf
Corroded
Light



2: Wing osf
Scratched
Over 25mm Thru Paint



3: Door osf
Dented
Between 10mm + 30mm



4: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



5: Door osf
Chipped
Edge Chip



6: Door osr
Scratched
UpTo 25mm Thru Paint



7: Wheel osr
Corroded
Light



8: Qtr Panel osr
Chipped
1 To 5



9: Bumper Rear
Scratched
Over 100mm Thru Paint



10: Wheel nsr
Corroded
Light



11: Qtr Panel nsr
Chipped
Edge Chip



12: Door nsr
Chipped
1 To 5



13: Wheel nsf
Corroded
Light



14: Bumper Front
Scratched
Over 100mm Thru Paint



15: Bonnet
Chipped
Multiple Chips



16: Roof
Chipped
1 To 5

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK