



VEHICLE INSPECTION REPORT

VA65UGE

Renault Clio 1.5 dCi 90 Dynamique S Nav 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	31/01/2016	Body Style	Hatchback	Last service miles	59,409
Year	2016	Keys	2	MOT Due	Expired
Mileage	93,122 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	DIESEL	Service documents	Service Book	Gears	5
Colour	SILVER	Number of stamps	6	Doors	5
VIN	VF15RKJ0A53449302	Last service date	01/07/2022		

£90 ADDITIONAL FEE

MOT expired

last service 1/7/22 @ 59,409 miles (6 services 3 main dealer) Driver side window faulty

Service due

Tyres

NSF	FALKEN	4.0mm
NSR	BUDGET	3.0mm
OSF	FALKEN	4.0mm
OSR	BUDGET	4.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- Service indicator
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- PAS
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Cloth seat trim

Photos






Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Door osf
Chipped
1 To 5



3: Wheel osr
Scratched
Over 50mm



4: Bumper Rear
Poor Previous Repair
Paint Flake



5: Tailgate
Dented
Over 30mm



6: Wheel nsr
Scratched
Over 50mm



7: Door nsr
Dented
Over 30mm



8: Door nsf
Scratched
UpTo 25mm Thru Paint



9: Wing nsf
Poor Previous Repair
Paint Flake



10: Wheel nsf
Scratched
Over 50mm



11: Bumper Front
Poor Previous Repair
Poor Paint



12: Bonnet
Chipped
1 To 5

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	Fault	Radio	OK
Sat nav	OK	Steering	OK