

VEHICLE INSPECTION REPORT

GJ12FFK

Kia Venga 1.4 CRDi 2 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	31/03/2012	Colour	BLUE	MOT Due	22/03/2027
Year	2012	VIN	U5YEH813LCL005993	Gearbox	MANUAL
Mileage	96,067 Miles Warranted	Body Style	Hatchback	Gears	6
Fuel Type	DIESEL	Keys	2	Doors	5

Low clutch


Tyres

NSF	MICHELIN	2.0mm
NSR	DUNLOP	3.0mm
OSF	MICHELIN	3.0mm
OSR	MICHELIN	3.0mm
Spare		

Features


- Rear parking sensor
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Remote central locking
- Rear wiper
- Air conditioning
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Radio/CD
- Front armrest
- Metallic Paint
- Traction control
- Alloy wheels
- Body coloured bumpers
- Front electric windows
- ABS
- Central locking

Photos





Condition Check



Damage Photos



1: Wing osf
Chipped
1 To 5



2: Door osf
Chipped
1 To 5



3: Door osr
Scratched
Over 25mm Thru Paint



4: Door osf
Chipped
Edge Chip



5: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



6: Bumper Rear
Chipped
Multiple Chips



7: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



8: Door nsf
Chipped
Multiple Chips



9: Wing nsf
Dented
With Paint Damage



10: Bumper Front
Scratched
Over 100mm Thru Paint



11: Bonnet
Chipped
1 To 5



12: Seat Base Cover osf
Scuffed
Over 25mm



13: Door nsr
Chipped
Multiple Chips

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK