



VEHICLE INSPECTION REPORT

HK68XYO

Ford Kuga 1.5 EcoBoost 120 Zetec 5dr 2WD

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	27/12/2018	Body Style	Hatchback	Last service miles	20,572
Year	2018	Keys	2	MOT Due	02/11/2026
Mileage	81,098 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Service Book	Gears	6
Colour	GREY	Number of stamps	3	Doors	5
VIN	WF0AXXWPMAR02338	Last service date	20/10/2022		

£100 ADDITIONAL FEE

LAST SERVICE 20/10/2022 @ 20,572 MILES (3 SERVICES) Noisy engine

Tyres


NSF	BUDGET	5.0mm
NSR	PIRELLI	3.0mm
OSF	BUDGET	5.0mm
OSR	MICHELIN	4.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Navigation system
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim

Photos





Condition Check




Damage Photos



1: Wing of
Chipped
1 To 5



2: Wheel of
Scratched
Up To 50mm



3: Door osf
Chipped
1 To 5



4: Door osf
Chipped
Edge Chip



5: Wheel osr
Scratched
Up To 50mm



6: Tailgate
Chipped
1 To 5



7: Bumper Rear
Scratched
25 to 100mm Thru Paint



8: Wheel nsr
Scratched
Up To 50mm



9: Door nsf
Chipped
Edge Chip



10: Bumper Front
Scratched
25 to 100mm Thru Paint



11: Bonnet
Dented
Over 30mm



12: Roof
Chipped
1 To 5



13: Door nsr
Dented
2 Or Less UpTo 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK