



VEHICLE INSPECTION REPORT

FY18NSZ

Ford Kuga 1.5 EcoBoost 182 ST-Line X 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	31/03/2018	Body Style	Hatchback	Last service miles	48,029
Year	2018	Keys	2	MOT Due	Expired
Mileage	57,832 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	GREY	Number of stamps	5	Doors	5
VIN	WF0AXXWPMAS23162	Last service date	18/07/2024		

Last Service: 18/07/2024 at 48029 miles. (5 services (3 main dealer))

Tyres




NSF	GOODYEAR	2.0mm
NSR	CONTINENTAL	2.0mm
OSF	GOODYEAR	2.0mm
OSR	CONTINENTAL	3.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Radio/CD
- Air conditioning
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Electrically adjustable drivers seat
- Rear headrests
- Passenger airbag
- Remote central locking
- Heated front seat
- Telephone
- Electric sunroof
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Door osf
Chipped
1 To 5



3: Door osf
Chipped
Edge Chip



4: Wheel nsr
Scratched
Over 50mm



5: Door nsr
Chipped
1 To 5



6: Door nsf
Chipped
1 To 5



7: Bumper Front
Scratched
25 to 100mm Thru Paint



8: Qtr Panel osr
Dented
Between 10mm + 30mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		