



VEHICLE INSPECTION REPORT

RE16ZWH

Nissan Juke 1.2 DiG-T Tekna 5dr

| Inspection | | Vehicle | |
|-----------------|----|---------|---------|
| Serious Damage? | No | VAT | Margin |
| | | V5 | Present |



Details

| | | | | | |
|-----------|---------------------------|-------------------|--------------|--------------------|------------|
| Reg. date | 18/05/2016 | Body Style | Hatchback | Last service miles | 58,349 |
| Year | 2016 | Keys | 2 | MOT Due | 04/06/2026 |
| Mileage | 65,583 Miles Warranted | Service history | Yes | Gearbox | MANUAL |
| Fuel Type | Petrol | Service documents | Service Book | Gears | 6 |
| Colour | SILVER | Number of stamps | 8 | Doors | 5 |
| VIN | SJNFEAF15U7229646 | Last service date | 16/05/2024 | | |

Last Service: 16/05/2024 at 58349 miles. (8 main dealer services) Noise from engine

Tyres


| | | |
|-------|----------|-------|
| NSF | MICHELIN | 3.0mm |
| NSR | NEXEN | 5.0mm |
| OSF | MICHELIN | 3.0mm |
| OSR | NEXEN | 5.0mm |
| Spare | | |

Features


- Bluetooth connection
- PAS
- Digital radio
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Alloy wheels
- Cruise control
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Central locking
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Remote central locking
- Park assist camera
- Audio remote control
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
Multiple Chips



3: Wheel nsr
Scratched
Up To 50mm




4: Door nsf
Chipped
1 To 5



5: Door nsr
Chipped
1 To 5



6: Wheel nsr
Scratched
Over 50mm




7: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



8: Bumper Rear
Chipped
Multiple Chips




9: Wheel osr
Scratched
Up To 50mm



10: Door osr
Scratched
Over 25mm Not Thru Paint



11: Door osf
Scratched
Over 25mm Thru Paint



12: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

| | | | |
|----------------|----|--|----|
| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
| Brakes | OK | Clutch Slip Test from Static | OK |
| Turbo Boosting | OK | Gearbox Static Gear Selection (engine running) | OK |
| Parking Brake | OK | No Excessive Smoking | OK |

| | | | |
|--------------------------|----|-------------------------------------|----|
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | Service indicator light illuminated | OK |
| ABS light illuminated | OK | | |
| Windows | OK | Radio | OK |
| Sat nav | OK | Steering | OK |