



VEHICLE INSPECTION REPORT

FN63UPK

Audi A3 1.4 TFSI SE 5dr

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 Present

nama
GRADE
3

Details

Reg. date	07/09/2013	Body Style	Hatchback	Last service miles	67,074
Year	2013	Keys	2	MOT Due	15/01/2027
Mileage	92,369 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Printout	Gears	6
Colour	RED	Number of stamps	6	Doors	5
VIN	WAUZZZ8V5EA020275	Last service date	31/08/2023		

LAST SERVICE 31/08/2023 @ 67,074 MILES (6 SERVICES) Seats stained



Tyres

NSF	MAXXIS	5.0mm
NSR	MAXXIS	5.0mm
OSF	MAXXIS	5.0mm
OSR	MAXXIS	5.0mm
Spare		

Features


- Bluetooth connection
- Telephone
- Air conditioning
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Cruise control
- Radio/CD
- Front armrest
- Metallic Paint
- Traction control
- Alloy wheels
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- ABS
- Central locking
- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Remote central locking

Photos







Condition Check



Damage Photos




1: Door osf
Chipped
Edge Chip



2: Door osr
Chipped
Edge Chip



3: Wheel osr
Scratched
Up To 50mm



4: Bumper Rear
Scratched
25 to 100mm Thru Paint



5: Wheel nsr
Scratched
Over 50mm



6: Qtr Panel nsr
Dented
With Paint Damage



7: Door nsr
Dented
Over 30mm



8: Wheel nsf
Scratched
Over 50mm



9: Bumper Front
Chipped
Multiple Chips



10: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK