



VEHICLE INSPECTION REPORT

LB15MYM

Peugeot 3008 1.2 Puretech Active 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	30/06/2015	Keys	2	CAP Clean	£1,400.00
Year	2015	Service history	Yes	CAP Average	£980.00
Mileage	84,311 Miles Warranted	Service documents	Service Book	CAP Below	£600.00
Fuel Type	PETROL	Number of stamps	7	Gearbox	MANUAL
Colour	SILVER	Last service date	17/04/2024	Gears	6
VIN	VF30UHNMYMFS154392	Last service miles	70,636	Doors	5
Body Style	Hatchback	MOT Due	14/04/2027		

last service 17/4/24 @ 70,636 miles (7 services 6 main dealer)

Engine unit replaced on 26/11/24 @ 72,136 miles Intermittent engine knock

Tyres

NSF	BUDGET	6.0mm
NSR	ZEETEX	5.0mm
OSF	BUDGET	6.0mm
OSR	MATADOR	5.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Central locking
- Cruise control
- Telephone
- Air conditioning
- Rear headrests
- Passenger airbag
- Remote central locking
- Heated front seat
- Radio/CD
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Door osf
Chipped
1 To 5



3: Wheel osr
Scratched
Up To 50mm



4: Bumper Rear
Chipped
1 To 5



5: Tailgate
Dented
Over 30mm



6: Qtr Panel nsr
Dented
2 Or Less UpTo 10mm



7: Wheel nsr
Scratched
Over 50mm



8: Wheel nsf
Scratched
Over 50mm



9: Bonnet
Chipped
1 To 5

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK